

**EDF 8.0-Ranked Turbines Scheduled for Removal**

<b>Turbine Label/ID Number</b>	<b>Location and Topographic Condition</b>	<b>Prior removals along String</b>	<b>Monitoring History</b>	<b>Fatality History</b>
1328/290	Down slope end row turbine	No prior removals along this string	9 searches	None
1325/287	Interior in a small saddle	No prior removals along this string	9 searches	None
1318/4546	Interior in a small saddle – next to 1319	No prior removals along this string	9 searches	None
1319/4545	Interior in a small saddle – next to 1318	No prior removals along this string	9 searches	None
306/1344	Down slope end row turbine	No prior removals along this string	51 searches	None
305/1343	Second from end row – next to 1344 on a slope	No prior removals along this string	51 searches	2 GOEA
1333/295	Down slope end row turbine	No prior removals along this string	61 searches	2 RTHA, 1 BUOW
1205/172	End row of 2-turbine string – next to 1206 on a slope	No prior removals along this string	50 searches	1 RTHA, 1 BUOW, 1 GOEA
1206/173	End row of 2-turbine string – next to 1205 on a slope	No prior removals along this string	50 searches	None
1211/178	Down slope end row turbine	Turbine (1207) on other end of string was previously removed	60 searches	1 RTHA, 1 BUOW
1210/177	Second from end – next to 1211 – on a slope	Turbine (1207) on other end of string was previously removed	60 searches	3 RTHA
1260/227	Down slope end row turbine	No prior removals along this string	60 searches	1 RTHA
1259/226	Second from end – next to 1260 on a slope	No prior removals along this string	60 searches	2 BUOW
1133/100	Down slope end row Turbine	No prior removals along this string	10 searches	1 BUOW
1164/131	Down slope end row turbine	No prior removals along this string	Monitored, but searches not indicated	1 RTHA
1157/124	Second to end in a draw	No prior removals along this string	10 searches	1 RTHA
1088/55	Down slope end row turbine	1087, the former end row turbine was previously removed	61 searches	1 RTHA, 1 BUOW
298/3402	Down slope end row turbine	No prior removals along this string	51 searches	2 AMKE, 1 RTHA, 1 BUOW
315/3419	Down slope end row	No prior removals along	51 searches	1 AMKE

	turbine	this string		
309/3413	Down slope end row with small notches	No prior removals along this string	51 searches	None
310/3414	Second from end row – next to 309 on a slope with small notches	No prior removals along this string	51 searches	None
323/3486	Isolated turbine on a slope above a draw	No prior removals along this string	51 searches	1 RTHA
81/3453	End row on a slope with notches and benches	80, the former end row turbine was previously removed from this string	51 searches	None
82/3454	Second from end row – next to 81 on a slope with notches and benches	80, the former end row turbine was previously removed from this string	51 searches	1 RTHA
83/3455	Interior, next to 82 on a slope with notches and benches	80, the former end row turbine was previously removed from this string	51 searches	1 RTHA
16/3342	Down slope end row turbine along a 10-turbine string	262, second from opposite end of 11-turbine string was previously removed.	60 searches	1 AMKE
252/3315	Down slope end row turbine along 3-turbine string	No prior removals along this string	51 searches	None
57/3451	Isolated turbine near a draw	No prior removals along this string	51 searches	None
180/3567	Middle turbine of 3-turbine string, in a saddle	No prior removals along this string	51 searches	None
166/3547	Down slope end row turbine along a 4-turbine string	167, the former end row turbine was previously removed from this string	51 searches	None
165/3546	Second from end row – next to 166 on a slope with notches and benches	167, the former end row turbine was previously removed from this string	51 searches	1 RTHA
176/3491	Down slope end row turbine along a 4-turbine string	No prior removals along this string	56 searches	1 RTHA
177/3492	End row of a 2-turbine string on a slope	No prior removals along this string	51 searches	None
178/3493	End row of a 2-turbine string on a slope	No prior removals along this string	51 searches	None
193/3579	Isolated turbine on a slope	Formerly an end row turbine, part of a 4-turbine string; but two	51 searches	None

		turbines, 194 and 196 were previously removed		
195/3581	Isolated turbine on a slope	Formerly an interior turbine of the 4-turbine string along with 193; but two turbines, 194 and 196 were previously removed.	51 searches	None
200/3599	Down slope end row turbine along a 4-turbine string	No prior removals along this string	51 searches	None
209/3603	Down slope end row turbine along a 4-turbine string	No prior removals along this string	51 searches	1 RTHA

**EDF Removed Turbines**

<b>Turbine Label/ID Number</b>	<b>Location and Topographic Condition</b>	<b>2010 HRT Ranking</b>	<b>Monitoring History</b>	<b>Fatality History</b>	<b>Probable rank of unranked turbines</b>
4402/2614	Down slope end row along 19-turbine string	none	None	None	8
4485/2644	Interior along 11-turbine string. On hill top above slope	7	None	None	
4486/2645	Interior along 11-turbine string. On hill top above slope.	7	None	None	
4487/2646	Interior on slope along 11-turbine string	7	None	None	
4488/2647	Interior on slope along 11-turbine string	7	None	None	
4489/2648	Interior on slope along 11-turbine string	7	None	None	
4490/2649	Interior on slope along 11-turbine string	7	None	None	
4506/2656	Up slope end row along 6-turbine string	6.99	None	None	
4511/2661	Interior within 19-turbine string. No obvious risk factors.	none	10 searches	None	6.99
4512/2662	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4513	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4514	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4515	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4516	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4517	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4518	Interior within 19-turbine string. No obvious risk factors	None	10 searches	None	6.99
4522/2672	Interior within 19-turbine	None	10 searches	1 RTHA	8

	string but along slope extending into canyon				
4523/2672	Third from end row, low on slope extending into canyon	None	10 searches	1 GOEA	9
4524/2673	Second from end row, low on slope extending into canyon	None	10 searches	2 GOEA	10
4530/2680	Up slope end row turbine along 5-turbine string	None	None	None	8
4534/2697	Second from end row, on slope above deep canyon	None	61 searches	1 AMKE, 3 GOEA	10
4546/2709	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	1 BUOW	8
4548/2711	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4549/2712	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	1 BUOW	8
4550/2713	Interior along 23-turbine string along ridge. No obvious risk factor, but near burrowing owl site	None	51 searches	1 BUOW	8
4551/2714	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4552/2715	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4553/2716	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4555/2718	Interior along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4556/2719	Third from end row along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site	None	51 searches	None	8
4557/2720	Second from end row	None	51 searches	1 BUOW	8

	along 23-turbine string along ridge. No obvious risk factors, but near burrowing owl site				
4606/2686	Interior along 8-turbine string extending downslope	None	None	None	7.5
4607/2687	Second from end row along 8-turbine string. Top of slope	None	None	None	7.5
4608/2688	End row turbine along 8-turbine string. Top of slope.	None	None	None	8
4609/2689	End row turbine along 5-turbine string	7.5	None	1 RTHA*	
4610/2690	Second from end row along 5-turbine string	7.0	None	None	
4611/2691	Interior along 5-turbine string. No obvious risk factors	6.99	None	None	
4612/2692	Second from end row along 5-turbine string. Above saddle	7.5	None	None	
4736/1632	Interior of 10-turbine string, but with vacant site on one side	7.5	61 searches	None	
4737/1633	Interior of 10 turbine string, but with vacant site on one side	7.5	61 searches	2 RTHA	
4740/1636	Interior of 10 turbine string	6.99	61 searches	None	
4741/1637	Interior of 10 turbine string	6.99	61 searches	None	
4742/1638	Second from end row along 10-turbine string	6.99	61 searches	None	
4743/1639	End row turbine along 10-turbine string	6.99	61 searches	None	
6651/5116	Top of slope end row turbine along 10-turbine string	6.99	9 searches	None	
6652/5117	Top of slope next to end row along 10-turbine string, probably in a small notch	7.0	9 searches	None	
6653/5118	Interior along 10-turbine string	6.99	9 searches	None	
6655/5120	Interior along 10-turbine string, probably in a small notch	7.0	9 searches	None	
6656/5121	Interior along 10-turbine	6.99	9 searches	None	

	string				
6657/5122	Interior along 10-turbine string	6.99	9 searches	None	
6659/5124	Second from end row along 10-turbine string on slope	7.5	9 searches	None	
6661/5126	End row of 2-turbine string on hill top	6.99	9 searches	1 BUOW	
6662/5126	End row of 2-turbine string on hill top, next to 6661	6.99	9 searches	None	
6663/5128	Upslope end row along 8-turbine string	None	None	None	8
6664/5129	Upslope next to end row along 8-turbine string	None	None	None	7
6666/5131	Downslope interior along 8-turbine string	None	None	None	7

\* assume this is an incidental find since the turbine was not monitored.